

STATE OF TEXAS WELL REPORT for Tracking #61028

Owner: Fuqua Cattle Company	Owner Well #: No Data
Address: 800 CR 392 Carlton, TX 76436	Grid #: 41-15-4
Well Location: CR 392; 1/2 mi from CR 388 TX 76436	Latitude: 31° 49' 18" N
Well County: Comanche	Longitude: 098° 14' 29" W
	Elevation: No Data
Type of Work: New Well	
	Proposed Use: Domestic

Drilling Start Date: **5/18/2005** Drilling End Date: **5/20/2005**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	10	0	50
	6.25	50	195

Drilling Method: **Air Rotary**

Borehole Completion: **Filter Packed**

	Top Depth (ft.)	Bottom Depth (ft.)	Filter Material	Size
Filter Pack Intervals:	65	195	Gravel	3/8

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	0	65	5 sax

Seal Method: **Pumped**

Sealed By: **Driller**

Distance to Property Line (ft.): **n/a**

Distance to Septic Field or other concentrated contamination (ft.): **n/a**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Water Level: **54 ft. below land surface on 2005-05-20** Measurement Method: **Unknown**

Packers: **benseal on top of gravel 65**

Type of Pump: **Submersible** Pump Depth (ft.): **170**

Well Tests: **Jetted** Yield: **60 GPM**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
No Data	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Dalton Drilling & Service**

**P O Box 208
Hamilton, TX 76531**

Driller Name: **Tom E Dalton**

License Number: **2850**

Apprentice Name: **Christopher Gilbert**

Apprentice Number: **1483**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	2	top soil & fill dirt
2	16	sandy clay
16	47	sand & gravel
47	51	sandstone & gray shale
51	65	sand,sandstone & shale
65	87	green shale & sandstone
87	97	hard sand & green shale
97	100	sandstone
100	126	red bed
126	129	sandstone & shale
129	139	red bed & red sandstone
139	143	sand & shale
143	157	red bed & sandstone
157	180	sand, sandstone & shale
180	191	sand, gravel & sandstone
191	195	r4ed & yellow clay

<i>Dia. (in.)</i>	<i>New/Used</i>	<i>Type</i>	<i>Setting From/To (ft.)</i>
8-5/8	used	Steel	for surface pipe 0 to 51
4-1/2	new	SDR 17 PVC	51 to 179
4-1/2	new	SDR 17 slot	179 to 195 .045

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**